

Wyoming Department of Transportation
Data Collection Manual

Table of Contents

1. General Information	1-1
A. Introduction	1-2
B. Policies	1-3
2. The Trimble TSC2 Data Collector	2-1
A. Introduction	2-2
B. TCS2 Keypad	2-3
C. Operating the Data Collector	2-3
D. Help	2-7
E. Operating Manuals	2-7
3. The Total Station and Trimble TSC2 Setup	3-1
A. Pre-Loaded Files	3-2
B. Trimble Desktop Screen	3-3
C. Total Station Setup	3-6
D. Survey Styles	3-8
E. Data Collector Jobs	3-18
F. Station Setup	3-23
G. Review the Measurement Data	3-29
4. Feature Codes	4-1
A. The Use of Feature Codes	4-3
B. The Survey Crew	4-4
C. Revisions to the Feature Code List	4-4
D. The WYDOT PS15 Feature Code List	4-4
E. Feature Code Changes	4-20

Table of Contents

5. Feature Code Illustrations.....	5-1
A. Introduction	5-2
B. Feature Codes	5-2
C. Feature Code Illustrations	5-3
6. The Data Collection Process.....	6-1
A. Project Control	6-2
B. Data Collector Settings.....	6-3
C. Data Collection	6-6
D. Check Shots.....	6-27
E. Collection Guidelines.....	6-32
7. Transferring Survey Data	7-1
A. Connecting to the Data Collector.....	7-2
B. Trimble Data Transfer	7-3
C. Transferring Files to the Data Collector	7-4
D. Transferring Files from the Data Collector	7-9
E. Transferring Data with Windows Explorer	7-11
F. Editing Survey Data.....	7-13
G. Reviewing Edited Data.....	7-13
H. Saving Edited Data.....	7-14
8. Mapping Survey Data	8-1
A. MicroStation.....	8-2
B. Geopak SS3	8-6
C. Measurement Files	8-12
D. Coordinate Files	8-19
E. Review Mapped Data.....	8-27
F. Mapping Errors	8-29
G. Correcting Mapping Errors.....	8-40
9. DNA 10 Digital Level	9-1
A. Raw Data	9-2
B. Equipment.....	9-2
C. Level Operation	9-3

- D. Collimation Error Correction 9-9
- E. Check and Adjust Procedure..... 9-10
- F. Line Leveling..... 9-23
- G. Allowable Misclosure..... 9-37
- H. Transferring Data 9-40
- I. Warning Messages 9-40
- 10. Submitting Survey Data 10-1
 - A. WYDOT Survey Files 10-2
 - B. Survey Data Submittal 10-3
 - C. Project Information 10-3
 - D. Archiving Files..... 10-4